

5		4	
	3	6	
	9 9		3
8 11 7			9 9
7		11)	5
10			





## TEST PROCEDURE TEST FIXTURE #FD1186

ASSEMBLE BYPASS ASSEMBLY
 BY-PASS PLUG ITEM 6 CAN BE ASSEMBLED TO BYPASS BODY IN ANY DIRECTION, BUT ENSURE ALL BY-PASS PLUGS ARE IN THE "OFF" (CLOSED) POSITION BEFORE TESTING.
 LOAD 5 BYPASS ASSEMBLIES ON TEST FIXTURE WITH PLUG LEVERS DOWNWARD (MALE PORTS WITH O-RINGS FIT INTO FIXTURE RECEPTACLES)

ACTIVATE FIXTURE

-PARTS ARE AUTOMATICALLY CLAMPED INTO FIXTURE AND SUBMERGED IN WATER
-40 PSI AIR PRESSURE IS APPLIED TO BOTH MALE PORTS ON BYPASS ASSEMBLY
-ALL 6 O-RINGS WILL BE TESTED IN THIS CONFIGURATION.

5. OBSERVE SUBMERGED PARTS FOR 20 SECONDS. A TIMER WILL TURN ON A LIGHT WHEN THE 20
SECONDS IS COMPLETED. THE OPERATOR WILL NEED TO RELEASE PRESSURE WITH YELLOW BUTTON.

6. CONSISTENT OR STREAMING AIR BUBBLES INDICATES FAILURE

## PACKAGING INSTRUCTIONS

FOLD AND TAPE CARTON BOTTOM #40130.
 INSERT 2 OF DIVIDER #40126 & 3 OF DIVIDER #40127 INTO CARTON. THIS WILL PROVIDE
12 SEPARATE COMPARTMENTS TO HOLD 12 BYPASS ASSEMBLIES.
 ENCLOSE EACH BYPASS ASSEMBLY IN THE "OFF" CLOSED POSITION IN A 8"X10" POLY BAG.

4. PLACE A BR19699 WITH EACH BYPASS

5. COVER WITH #40128 PAD.

6. LAY WARRANTY SHEET ON TOP OF PAD, CLOSE AND TAPE BOX.
7. PLACE LABEL ON SIDE OF CARTON SO THAT LABEL CAN BE READ WHEN BOXES ARE STACKED.
- REFERENCE PENTAIR PROCEDURES #OP-06 & #PURWI-01 FOR LABEL CONTENT & DISPLAY.

## PACKAGING MATERIALS

CARTON QTY: 1 3 SLOT DIVIDER #40126 QTY: 2 2 SLOT DIVIDER #40127 QTY: 3 #40128 PAD QTY: 1 WARRANTY SHEET POLY BAG, 8" X 10" CARTON LABEL, 4" X 6" #40957 QTY: 1 QTY: 12 QTY: 1


ITEM NO.	QTY.	PART NO.	DESCRIPTION
1	2	18660	O-RING, -213
2	2	18662	RING,RETAINING , BY-PASS
3	2	41106	SEAL, RETAINER, BY-PASS, 3/4"
4	1	41107	BODY, BY-PASS, 3/4"
5	1	41108	PLUG, BODY, BY-PASS, 3/4"
6	2	41109	PLUG, BYPASS 3/4" PLASTIC
7	2	BR13305	O-RING, -199
8	2	BR13314	SCREW, HX WASHER HEAD, 8-18 X .60
9	4	BR18661	O-RING, -218
10	1	BR19699	HOSE BARB, 45 DEG -1/2 NPT

ROHS DIRECTIVE 2002/95/EC, WEE DIRECTIVE 2002/96/EC, AND ELV DIRECTIVE 2000/53/EC. THESE DIRECTIVES RESTRICT THE USE OF LEAD, CADMIUM, MERCURY, CHROMIUM, PBB, PBDE, AND OTHER HAZARDOUS MATERIALS. SEE THE TERMS AND CONDITIONS OF THE CONTRACT (PURCHASE ORDER) FOR MORE INFORMATION.				S MATERIALS.
	All drawings and specifications as well as processes, materials, compounds and other similar criteria are to be strictly adhered to. No modifications allowed without prior written approval.	THIRD ANGLE PROJECTION	Pentair Water F 140, Av Rolland C	
		DENOTES CRITICAL DIMENSION DENOTES REVISION	Pentair Water	78532 Buc cedex France

THE COMPONENT, PART, OR ASSEMBLY DESCRIBED IN THIS DOCUMENT MUST COMPLY WITH THE FOLLOWING EU (EUROPEAN UNION) DIRECTIVES:

as processes, materials, compounds and other similar criteria are to be	PROJECTION P			Pentair	1/ A A D	140, Av Rolland Garros	
strictly adhered to. No modifications allowed without prior written approval.	DENOTES CRITICAL DIMENSION DENOTES REVISION			Water	_		
TOLERANCES (UNLESS OTHERWISE SPECIFIED)	Material		Title				
25.0 ±0.5 mm 25.00 ±0.10 mm ANGULAR ±1°	NA			BYPASS ASSEMBLY, 3/4" PLASTIC			
✓ 3.2	Drawn	Date (dd/mm/yy)	Scale	Filename	Weight (kg)	Sheet	
Break all exposed sharp corners 0.25 x 45° max.	CHT	21/05/08	1:1	BU60049	X	1 of 1	
DO NOT SCALE DRAWING DIMENSIONS = MM [inch]	Approved LD	Date (dd/mm/yy) 21/05/08	Size A2	Part # BU60049	Dwg #	BU60049	
<u> </u>		1					

11 2 BU13255 CLIP, MOUNTING



ITEM	QTY	PART NO.	DESCRIPTION	NOM
1	2	18660	O-RING, -213	JOINT TORIQUE
2	2	18662	RING,RETAINING , BY-PASS	BAGUE DE MAINTIEN
3	2	41106	SEAL, RETAINER, BY-PASS, 3/4"	PLAQUE DE RETENUE JOINT
4	1	41107	BODY, BY-PASS, 3/4"	CORPS BY-PASS 3/4"
5	1	41108	PLUG, BODY, BY-PASS, 3/4"	BOUCHON
6	2	41109	PLUG, BYPASS 3/4" PLASTIC	PLUG BY PASS 3/4" PLASTIC
7	2	BR13305	O-RING, -199	
8	2	BR13314	SCREW, HX WASHER HEAD, 8-18 X .60	VIS
9	4	BR18661	O-RING, -218	JOINT
10	1	BR19699	HOSE BARB, 45 DEG -1/2 NPT	COUDE 45° - 1/2 NPT
11	2	BU13255	CLIP, MOUNTING	CLIP

